

20-00572

HYDROFOILER SL3

DISPLAY/THROTTLE UNIT

RELEASE NOTES

Introduction

This document communicates the latest features and changes in the SL3 display control software.

Software part number 000753.

This software operates within the Display -Throttle Unit of the SL3 hydrofoil bike.

Latest Release Version V0.28 (01/05/2023)	
New and improved	Bike status menu added: <ul style="list-style-type: none"> Total hours and minutes of bike usage Last error code (if any occurred) Firmware version numbers for bike, display and battery Bike mode (default only)
Fixes	<ul style="list-style-type: none"> None

Release Version V0.27	
New and improved	<ul style="list-style-type: none"> E10 error code added for battery comms failure. Errors show for 5 seconds on screen if occur while riding.
Fixes	<ul style="list-style-type: none"> Temperature icon now shows when above temperature occurs. E26 now does not occur randomly on powerup. E32 occasionally, display bug

Release Version V0.22	
New and improved	<ul style="list-style-type: none"> Logs now include Last Error code. Fixed display states - always goes to --- when motor off 30 sec timer expires
Fixes	<ul style="list-style-type: none"> Error log download works correctly.